

Personal contact details and Professional summary	
Name	Mr. Michael Connelly Chartered Senior Structural Engineer
Address	DBFL Consulting Engineers Ormond House Upper Ormond Quay Dublin 7
Contact details	Landline telephone: +353 1 400 4000 Mobile: +353 86 156 4887 Email: Michael.Connelly@dbfl.ie & mpdconnelly@gmail.com Website: www.dbfl.ie
Qualifications	BEng (Hons) CEng MIEI
Career history	Sep 1999 – Mar 2003: Graduate Structural Engineer, Shire Consulting, Worcs, UK April 2003 – Nov 2003: Structural Engineer, Carlbro, Dublin Nov 2003 – Present: Senior Structural Engineer, DBFL, Dublin
Relevant project experience	<p>Residential Units at Drynam, Beau Park, Myrtle, North Dublin</p> <p>Carried out in excess of 100 visual inspections and coordinated up to 15 engineers to carry out visual inspections of circa 700 properties affected with pyritic stone infill.</p> <p>Wrote reports for in excess of 500 of these properties based on visual inspection findings and tests results on stone infill.</p> <p>Inspected and certified remedial works for in excess of 50 of these properties, gathering evidence for lawsuit against stone supplier during the works.</p> <p>Residential Units, Kilmessan, Co. Meath</p> <p>Carried out visual condition inspections and wrote reports for circa 30 affected properties. Inspected and certified remedial works.</p> <p>Residential Units, Dromheath, Dublin 15</p> <p>Carried out visual condition inspections and wrote reports for circa 25 affected properties.</p> <p>Primary School, West Dublin</p> <p>Carried out visual condition inspection of school suspected to be affected by pyritic stone infill, producing report on same.</p>

Building Condition Assessments (BCA's)

Carried out numerous Building Condition Assessments (BCA's) for properties suspected to be affected by pyritic stone infill, in accordance with Irish Standard IS 398.

Specific areas of expertise

- The identification of hallmark pyrite related damage.
- Visual condition inspections and report writing on properties affected by pyritic stone infill.
- Carrying out Building Condition Assessments (BCA's) in accordance with IS 398.
- Specifying, inspecting, and certifying remedial works for pyrite related damage.

The Engineers Ireland Pyrite 'Design Professionals' (DP) Register

Declaration: *I accept responsibility for the accuracy of the particulars contained in this form including my qualifications and I agree that, when submitted, its contents will be made available on the Engineers Ireland website www.engineersireland.ie*

I agree to the declaration above